of a mile away. There had, too, been an assertion that the site of a famous battlefield would be submerged, but Captain Reid was able to refute it by proving that the battlefield in question was no less than nine miles away from where it is sought to form the reservoirs. As a result of the debate, an amendment to refer the Bill to a Committee with special powers was negatived by 276 votes to 91, and the Bill was read a second time.

Tariffs and Trade.

The introduction of a Bill by the Govern ment of Belgium during the month for raising considerably the import duties of foreign goods is a characteristic example of the policy of retaliation which is being forced upon some countries by the commercial exactions of others. Having always adopted liberal trade principles, Belgium found herself placed at a great disadvantage in the negotiations being carried out with France for a commercial treaty. The object of the separate treaties formulated by the French Government is to secure special advantages for the many new industries that have been created during the past few years particularly in the way of opening up markets in countries which are offered reciprocity in favour of goods that do not compete seriously with French products, and when industrial interests clash, as is the case with Belgium, there is obviously no way out of the difficulty except by a change of fiscal policy which will enable Belgium to offer reciprocal advan-As a matter of fact, Belgium aims at treating with France on the basis of facilitating imports of essentially French goods in exchange for lower tariffs on Belgian manufactures entering France. For that reason the proposed Belgian duties will be a serious burden upon the essentially French products which bulk so largely in foreign trade, unless the French Government accepts an arrangement whereby foreign engineering goods are allowed to enter the country under favourable tariff conditions. The negotiations have shown the French Government that it is practically impossible to develop a foreign trade and at the same time adopt a rigid policy of protection for certain branches of the engineering trades which cannot exist in face of foreign com-For the time being those industries are favoured to a certain extent by the currency depreciation; but the advantage is only temporary, and the considerable changes that may take place in the future will certainly upset any commercial arrangement which aims at conferring one-sided benefits. The progress of negotiations between France and Belgium will show whether it is possible in present circumstances to fix upon a reciprocal basis for commercial treaties.

The Vindication of the Therm.

As everyone who had any real knowledge of the matter imagined would be the case, the Departmental Committee appointed by the Board of Trade to inquire into the therm basis of charging for gas declared itself to be in favour of that much-maligned unit. In fact, it not only recommended, in a report published during the month, that the therm system should be continued, but suggested that it should be extended to all statutory gas undertakings within the scope of the Gas Regulation Act. The inquiry certainly did good, in that irresponsible and ignorant critics are no longer able to accuse gas authorities of unfair dealing with their customers, and it seems not unlikely that to it the recent reductions in the price of gas may be, indirectly, attributed. Suppliers of gas have been reviewing their charges, with the result that there have been reductions in various directions to the benefit not only of the consumers, but of the shareholders as well, who have been faring unhappily during the period of high charges which have automatically resulted in reduced dividends, for, as our readers are aware, the dividends of gas undertakings vary inversely with the price of the gas. Dr. Charles Carpenter, the president of the South Metropolitan Gas Company, recently stated at a meeting of shareholders that there was nothing wrong about the therm, but that there had been with the price charged for it. If the suppliers have been tardy in reducing the price, the shareholders have had more cause to complain than the consumers, for they have been doubly taxed. They have not only had to pay a high price for the gas they have burned, but have received smaller returns from their investments. It is only just recently that the dividends of gas companies have begun to approach pre-war figures, but hopes are felt in many quarters that, before very long, the price of the therm may be so far reduced that gas may become as cheap as it was nine years ago.

The Stadium in Wembley Park.

THE Stadium which is being built in Wembley Park in connection with the British Empire Exhibition of next year, is nearly completed, its erection having been specially expedited in order that the structure been specially expedited in order that the structure may be available for the Football Cup Ties Final on April 28th. The photograph taken from an aeroplane, which is reproduced in Fig. 1, hardly gives an adequate idea of its size, for it is a large and imposing building, which has been designed to provide, under cover, sitting accommodation for 25,000 persons, in ring seats for 10,000 persons, and standing room for an additional 1,500, at that it is capable of holding no fewer than 91,500, so that it is capable of holding no fewer than 126,500 people, all of whom will have a practically uninterrupted view of the whole of the arena. A plan of the building is given in Fig. 2. The arena itself, which is intended for both sports and games, has in its centre an absolutely level round-ended oblong of grass which measures 492ft. long—for some 375ft. of which the sides are parallel—and 260ft. wide. In passing, we may say that we understand the ground on which the Final Cup Tie is to be played will measure 115 yards—or 345ft.—long by 75 yards—or 225ft.—wide, so that the area provided is more than ample for the purpose, as was, of course, intended that it should be. We may here remark intended that it should be, we may here remark too—though it has nothing whatever to do with engineering—that the grass, the turves of which were obtained in various portions of the estate, and were laid as long ago as September last, is really in excellent condition. Encircling the grass is a flat and level cinder running track, about half of which

to which reference will be made later; but whether or not that will be permitted we cannot say. The difference in vertical height between the lowest and the highest steps is just over 16ft. 6in. In order, apparently, to prevent rushes from the top to hottom of these terraces of steps, and of compelling the use of these terraces of steps, and of compelling the use of the gangways, three rows of barriers have been formed between each of the latter. Their arrangement will be seen in Figs. 10 and 13, page 368. They consist of steel pipes fixed horizontally at a height of about 4ft. above step level and carried at their ends and at intervals in their length by angle iron brackets of inverted V shape. The steps, the treads of which are filled in with coarse clinker at the bottom and a topping of 11in. of fine cinders, have in some and a topping of 14m of fine cinders, have in some parts been formed directly on solid ground, the soil being given the necessary slope; but where the original contours of the land did not permit of that being done—and that was the case in the major portion—filling-in had to be resorted to. Although in selecting the site for the Stadium advantage was taken as much as possible of favourable contour. taken as much as possible of favourable contour lines, a very considerable amount of excavation had to be carried out. In fact, for one purpose and another, as many as 120,000 cubic yards of material mostly yellow clay—had to be removed, and an equal amount used in filling. As will be seen from the plan given in Fig. 2, the original ground level of the arena site varied between 165.5ft. above Ordnance Datum at the east end to something over 180ft. above Ordnance Datum at the west end, with intervening eminences above the average between these two figures coming in between. The excavation was, to a large extent, done by a Bucyrus drag-line excavator. We may here say that the clearing of the site was started



FIG. 1-VIEW OF THE WEMBLEY STADIUM FROM THE AIR

42ft. wide, the remainder being 18ft. wide. dimensions are such that a line drawn at a distance dimensions are such that a line drawn at a distance of lft. from the edge of the track right round the oblong measures exactly one quarter of a mile in length, so that four laps constitute a mile. A feature, length, so that four laps constitute a mile. A feature, to which we shall refer in more detail later, is that, by making special arrangements, in accordance with a decision arrived at after the building operations had been actually started, a perfectly straight and level track, 220 yards—i.e. just over 200 m.—long, has been provided, and it is, we believe, the only straight cinder track of that length in this country.

Immediately encircling the running track, a strip of ground just over 11ft. wide, which is enclosed both in front and behind by an iron ring fence, is to be devoted to five rows of "special ring seats" arranged arranged devoted to five rows of "special ring seats" arranged at three levels, and supported on blocks of concrete. We understand that, when the arena is not being used for racing pruposes, seats of various heights will also be placed, temporarily, over a certain width of the running track itself, so that, at times, there have been a many beautiful and the control of the may be as many as ten rows deep of these "special ring seats." For a width of nearly 56ft. 6in. right round the inner fence of the ring seats enclosure, tiers of forty-eight steps are formed, the steps being just over lft. 2in. wide, the risers varying from $3\frac{1}{2}$ in. in the lower rows to $4\frac{1}{2}$ in. in the upper rows, and being formed by means of 5in. by 2in. timbers set on edge. This oval annulus—if such an expression be permitted—will be for standing spectators only, and there will be no cover. For obtaining access to these terraces of steps there are forty-nine openings formed in the wall enclosing them and nine radial gangways. Access is also possible by way of the main tunnel which leads directly into the arena, and

in February, 1922, and that the work is now complete.

In February, 1922, and that the work is now compact.

The actual building operations, which are now virtually finished, occupied less than a year.

It is around the outermost of the terraces of steps referred to above that the building proper of the Stadium may be said to commence. All round steps referred to above that the building proper of the Stadium may be said to commence. All round the building there is a practically uninterrupted series of thirty-one terraces of concrete steps measuring 2ft. 2in. wide and having rises of 1ft. 1in. These steps are formed in the manner shown in the drawing. Fig. 6, and in Figs. 3 and 4. They are erected on bearers consisting of 14in. by 6in. by 46 lb. and 57 lb. rolled steel joists spaced generally at 14ft. 4in. centres. The joists which are set at a slowe of 2 to 1 with the The joists, which are set at a slope of 2 to 1 with the horizontal, are supported at their lower extremities by being attached to the reinforced concrete wall which stands on a solid concrete foundation, and is built round the outside periphery of the ramp of steps first mentioned—see Fig. 5. At their upper ends they are supported by the outside wall of the Stadium, which will be referred to later. These joists are at three points in their length connected together by lattice girders to which they are riveted, and by lattice girders to which they are riveted, and every third joist is supported at the junctions of the joists with the girders by steel columns of increasing heights. These columns—see Figs. 5 and 6—are made of steel channels and lacing bars, and they are spaced radially at 17ft. 4in. centres. The tallest of these columns is 32ft. high and the shortest 16ft. high. In the shortest there are two 9in. by 3in. channels; in the intermediate two 10in by 3in. channels; in the intermediate two 10in. by $3\frac{1}{2}$ in. channels; and in the tallest two 11in. by $3\frac{1}{2}$ in. channels, the lacing bars in all cases being $2\frac{1}{2}$ in. 0 $\frac{1}{2}$ in. These columns are erected on solid concrete foundations taken well down into virgin ground. It may here be stated that the tops

of these foundations came just above the floor of a concrete corridor which stands at a level of 174.75 above Ordnance Datum. This corridor, which runs at the same level practically all round the Stadium, will be referred to later. The two outer rows of columns are braced together, and the outermost row is braced to the outer wall in the manner shown in the engravings. The risers of the steps are formed of pre-cast reinforced concrete beams 14ft. 3in. long

high, and 13in. by 13in. in cross section for the major portion of their length, but increased in dimensions at the top and bottom. There are sixteen of these supporting columns on the south side of the arena all spaced at equal distances apart—i.e., 43ft. On the other side of the arena there are only twelve columns for the same length of roof. For the five columns and can for no furture comments.

—and can for no f

so that the roof actually projects for some 20ft. beyond the line of actually projects for some 20th beyond the line of the columns. The arrangements are well illustrated in the various engravings—see Figs. 5, 6 and 7 and in Figs. 10, 12 and 13, page 368—and call for no further comment.




FIG. 2-GENERAL PLAN OF THE STADIUM SHOWING THE ORIGINAL CONTOUR LINES OF THE SITE

by 4½in. wide and 1ft. 4½in. deep, set on edge.

The is as much as 130ft., and that between each of them by 4½n. wide and ltf. 4½n. deep, set on edge. The ends of these beams rest on specially shaped pressed and the next column outwards is 86ft. The wide steel knee pieces of the steel joists—see Fig. 6. No less than 5000 of these beams were required. The treads of the steps are formed of reinforced concrete the structure or the view from the Royal box or balcony which comes exactly in the centre of the rolling which will provide sitting accommodation. The steps the view of the arena from the Press gallery, which,

parts of the oval, since they had to be taken over the top of the banqueting hall, the span of the ceiling of the main bay of which is 34ft. Sin. from centre to centre. The construction will be readily understood from the drawing. The banquetting hall is a large room which measures 215ft. long by 70ft. wide, and from it doors lead on to a wide terrace which runs along the north face of the building. As many as 1000 persons will be able to be seated at one time. The floor of the




FIG. 3-VIEW SHOWING ERECTION OF TERRACES OF CONCRETE STEPS

FIG. 4-CONCRETING TREADS OF TERRACED STEPS

situated in the centre portions of the covered areas have been furnished with lift-up wood seats each 16in. wide. In the wing portions of the covered area sitting accommodation is provided by means of planed wood planks fastened to the concrete treads. The roofs have steel framework, covered with corrugated asbestos sheets. The principals are supported partly by the outside wall and partly by means of pre-cast octagonal reinforced concrete columns 32ft.

as will be seen from Fig. 8, comes immediately behind, room stands at an elevation of 174.75ft. above Ordbut at a considerably higher level than the Royal box. The three columns where the wider spacing comes are stouter than the other columns, and measure 15in. by 15in. in cross section. They are, however, otherwise identical with the others. Resting on the caps

room stands at an elevation of 174.75ft. above Ord-nance Datum, that is to say, at the same level as the corridor, mentioned above, which runs right round the building. Immediately over the hall and at a height of 25ft. above it is a tea room, which is also a large room that will be able to accommodate 600 records at a time.

The Royal box or balcony, the floor of which stands at a height of about 21ft. above the grass in the arena,

THE STADIUM IN WEMBLEY PARK

MESSRS. JOHN W. SIMPSON AND MAXWELL AYRTON, ARCHITECTS, AND MR. E. O. WILLIAMS, ENGINEER




FIG. 5-TYPICAL CROSS SECTION THROUGH SOUTH FACE OF THE BUILDING




FIG. 6-ARRANGEMENT OF ROOF, TIERS OF STEPS, AND STEEL WORK




FIG. 7-DETAILS OF REINFORCED CONCRETE ROOF-SUPPORTING COLUMNS

SWAIN SC

is approached by means of five flights, having a total of forty-seven steps, from a tunnel formed from the north face right under the main building and giving access at the other end to the arena. This tunnel, which is 40ft. wide, varies in height from 20ft. at the entrance to 13ft. at the exit, has a concrete arch at

The whole building is constructed of concrete on a steel skeleton. A noteworthy feature is that fluted shuttering has been employed with excellent effect, shuttering has been employed with excellent effect, the somewhat distressing monotony of large areas of concrete facing having been practically entirely avoided, the employment of horizontal V-shaped

the corridor level. Then at an elevation of 25ft. above the corridor is a gallery with a reinforced concrete floor, about 16ft. wide, which runs from end to end of the south portion of the building which is roofed over. It is reached by a series of double stairways of reinforced concrete, which are built at intervals of 150ft. From that corridor flights of ten steps lead up to openings formed at intervals of 50ft. in the tiers of concrete steps.

n O Level (2033) Level (199 75)

FIG. 8-CROSS SECTION THROUGH BUILDING ON NORTH FRONT

channels in the material aiding in the effect advantage of the fluted shuttering is that the dis-figuring marks which are usually caused by the divisions in ordinary shuttering have been almost completely done away with. Imposing features of the front are two concrete towers which rise to a height of 106ft. 4in. above the terrace, and reach to over 280ft. above Ordnance Datum, being surmounted by a reinforced concrete flagstaff rising to a further height of 22ft. 6in. to the underside of the trucks, which are fashioned in the form of Imperial crowns,

and are also of reinforced concrete.

The outside wall of the Stadium, saving where the building on the north face—just described—comes, is formed of a series of nearly semi-circular arches carried on vertical piers. The piers arise to a height of 25ft, above the corridor, and the height to the crown of the arches is another 20ft. 6in. The arches vary slightly in span according to their positions and vary slightly in span according to their positions and to the amount of curvature of the outside face of the wall at the points where they occur. The average span is, however, about 50ft. Both piers and arch ribs are of reinforced concrete cast in situ. Expansion joints are provided at intervals of four arches, and where they come the break is made at the centre of the crown of the arch. In such cases, of course, the two halves of the arch are cast separately and act as cantilevers. In a majority of cases the arches are simple, but, where extra loads from roof have to be taken, a 20in. by 12in. reinforced beam is arranged on the tops of the piers at springing level. In such cases two equally spaced spandrel posts connect the top of the beam with the soffit of the arch. Expansion joints are also formed in these beams where the joints joints are also formed in these beams where the joints in the arches come. The dimensions of the piers vary with the weight they have to carry, but the cross section of the majority is 3ft. by Ift. 8in. They are erected on solid foundations with wide stepped footings taken well down into virgin soil. Only at one place has a retaining wall been formed, and that is at the south-east end, where the building approaches nost nearly to the Great Central line, which at that point is in a somewhat deep cutting. This wall, as well as the railway line, can be seen in the view from the air given in Fig. 1. Above the crown of the arch the wall is taken up for another 7ft. 2½in. by means of pre-cast concrete blocks and a surmounting reinforced concrete beam 12ft. by 12in., and it is to the latter that the roof principals are attached. The top of the wall therefore reaches a height of 52ft. 9½in. above the level of the corridor or 227ft. 6½in. above Ordnance Datum.

The level of the corridor is, as has been said, 174.75 above Ordnance Datum, or at 9.83ft, above the running track which stands at 164.92 above Ordnance Datum. Access to the corridor from the outside is obtained by means of five separate flights of reinforced concrete steps, while the terrace on the north forced concrete steps, while the terrace on the north front, which is practically at the same level as the corridor, is reached by means of two sets of forty reinforced concrete steps which are about 25ft. wide. It is from the corridor that all parts of the Stadium are approached. First of all there are round the periphery of the inner ramp of standing places the forty-nine concrete openings formed in the dwarf wall, which are reached by flights of ten steps up from

means of a tunnel, the floor of which is at the same

level as the running track.

Mention was made above of the tunnel which has been formed through the structure of the Stadium in order to provide a straight track one furlong—220 yards—in length. The flexibility of concrete construction is well exemplified in the arrangements which have been made. The tunnel is some 24ft. wide, and since it was necessary to make provision for carrying not only the weight of the superposed structure but also that of the spectators, specially designed reinforced concrete beams had to be worked in. These beams measure 3ft. by 2ft. and they are connected together by means of cross beams which carry the floor of the corridor. The length of the

million); 25,000 tons of concrete, using 3500 tons of Portland cement; 14 miles of concrete beams to form the terracing in the stands.

The concrete in the north or main front has been ad still is being placed by means of an "Insley" and still is being placed by means of an "Insley" tower. The tower is of light steel work and is 160tt. high, and may be seen'in Fig. 9 and in Fig. 11, page 368. It carries a long movable jib from the end of which is suspended a balanced truss which can be turned in any direction. There is a hopper near the top of the tower and from it leads a chute to a further hopper on the truss, along which is taken another chute.
The concrete is mixed at ground level in a machine, is lifted in a box, which travels in guides arranged inside the tower. When the level of the top hopper inside the tower. When the level of the top hopper is reached the concrete is tipped from the box into the hopper and thence finds its way by gravity to the delivery end of the balanced truss. The material can be deposited at any desired point within a radius of 400ft, from the tower, so that an area of something over 114 acres can be covered

We may say that the building has undergone some severe tests, and though the results have not yet been completely worked out, we believe that they will prove to be eminently satisfactory. Some of the deflections measured, have, at any rate, been well within permissible limits. The tests were made with both dead and live loads. The dead load consisted of bags of sand and the load imposed was about 60 per cent. in excess of the load which is to be 60 per cent. in excess of the load which is to be expected in actual service. On the occasion of one of our visits a dead load of 300 tons was in position on the centre of the curve at the east end. It so happened that on the same day the live load test was applied. A body of workmen released for the time being from their labours on the site, and numbering, we were given to understand, 1280, was first of all drawn up outside the building and then marched in, in companies, and led to the banks of seats immediately in companies, and led to the banks of seats immediately behind the Royal box, where they closely filled a section of the seats right up to the topmost level. It was quite obvious that the great majority of these men had seen service in the war, for otherwise we do not think that it would have been possible, without preliminary drill—which they had not had—for them to act in unison with such wonderful precision as was actually the case. Under the command of Captain F. B. Ellison, who, during the course of the work, has been resident architect, the men were put through a series of movements, such as standing up, sitting down, swaying from side to side and backwards and forwards, and marking time, all of which had to be, and actually were, done to time. The men appeared to the onlooker to be wonderfully together in their movements, and the whole business must have been a very useful test. Then the instructions were to designed reinforced concrete beams had to be worked in. These beams measure 3ft. by 2ft. and they are shout and jump about and wave the arms frantically so as to reproduce as nearly as possible the movements carry the floor of the corridor. The length of the tunnel is nearly 150ft., and for that part of the distance



FIG. 9-BUILDING ON NORTH FRONT UNDER CONSTRUCTION

the competitors will, in consequence, run under cover. Perhaps at this point a word as to the excellence of the cinder track throughout may not be out of place.

As giving some idea of the immense size of the undertaking, we may say that the overall length of the Stadium on its major axis is 900ft, and that the maximum overall width is 650ft. The following is a list of the quantities of the various materials used:—1400 tons of structural steel work; half a million rivets, for which one and a-half million holes had to be drilled; 600 tons of steel rods for reinforcing the concrete (total length of these rods is about 500 miles, and the total numbers of the rods one-quarter of a

at a point not quite opposite the Royal box; just outside the eastern end of the covered area, in fact. Then the men were marched along the steps until they came beside the portion which was loaded with dead weight. There, further movements were gone through, including marking time at the double—an experience which the structure is never likely to have to undergo when fulfilling its usual functions. Finally gangs of the men were ordered to run down several flights of the steps. In every case, as was, of course, anticipated, the test was without visible result, there being no sign of weaknes

The architects of the building are Messrs. John